


# RED ZONES ARE NO ZONES



- Stay alert and stay out of the way. Always assume that the equipment operator can not see you.
- Stay out of equipment red zones.
- Never lean or rest against equipment. You could be electrocuted.
- Never get between two pieces of equipment.
- Never approach equipment until it has stopped moving and the operator is aware of your presence. Get and maintain eye contact with operator when approaching equipment.
- Never be a passenger on equipment unless it is equipped for passengers.
- Use extra caution around blind spots in the mine area such as turns or intersections.
- Never work on equipment that has not been properly shut down and locked out.

