

Welding & Cutting Safety Underground Mines



- **Only perform under the supervision of a qualified person.**
- **Continuously test for methane gas immediately before and during.**
- **Always evaluate the area for hazards and remove from area.**
- **Always wear proper personal protective equipment.**
- **Always ensure rock dust and suitable fire extinguishers are immediately available.**
- **Conduct a diligent search for fire during and after.**