

DANGER!

FALLING OBJECTS

Prevent **injuries or death** from overhead work.


🧑‍🔧 Never allow workers to stand or work in areas below work area.

🧑‍🔧 Barricade or rope off the area to keep workers below clear of the work area.

🧑‍🔧 Post warning signs.

🧑‍🔧 Keep tools and other materials away from edges and off railings.

🧑‍🔧 Install toe boards around perimeter of overhead work area.



**DANGER
OVERHEAD WORK**

**HARDHATS
REQUIRED**